

Ryan's Express

Ryan Company, Inc. Newsletter - Feb 2007

BOILERS • WATER HEATERS • BURNERS • CHIMNEYS • ACCESSORIES

In This Issue

» NEW Products

- Fulton Skid Units
- Lochinvar Knight Boiler
- » Rules of Thumb
- » What's Wrong?
- » More Free Money
 - Xcel Energy Rebates
- » Featured Job
 - Metro Transit Police
- » What's Wrong? Answers

Did You Know?

Burnham Boiler's parent company, Burnham Holdings, Inc is traded on the OTC market as BURCA. Based on \$16.95 share price, Burnham's dividend yield is 4.01%.

Useful Formulas

1 Boiler Horsepower (BHP) = 33475 BTU Output

 $\Delta T = \frac{BTU \text{ Output}}{(GPM)(60)(8.33)}$



Ryan Company, Inc. 3361 Republic Ave St. Louis Park, MN 55426 Phone (952) 915-6475 Fax (952) 915-6480 www.ryancompanyinc.com

NEW Products

Fulton Skid Mounted Units

Make your installations easy. Fulton will package and skid mount components to make your life simple. Unit shown has: boiler, air separator, pump, heat exchanger, expansion tank and piping.



Lochinvar Knight Boiler



- Modular
- High Efficiency / Condensing
- Modulating with 5:1 Turndown
- Built-In Sequencer Controls up to 8 units
- Seven Models: 80-500 MBH
- PVC Vented







Rules of Thumb




- Old Boiler Capacity: Use 5 SqFt of heating surface per Boiler Horsepower.
- Quick Load Calculation: For a conservative estimate use 50 BTU's per SqFt of building area.



What's Wrong?

(Answers on Page 2)



How's Your Record Keeping?

We have Kewanee boiler records back to the 1920's.

8/15/23 1-5K-15# 9/22/32 1-307 Replacement 7/13/35 1-1752 High School 11/13/40 1-743J 11/3/41 1-0742J Bakery 4/13/46 1-7L73 Schoens Furniture Store 1/25/47 1-387 2/2/48 2-5184 School 7/65/69 1-HM25(100#) South Shore Co-op Creamery 6/16/50 1-3R5M American Legion #97 7/6/50 2-582 Municipal Hospital 10/9/52 1-3R5M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church 1/15/52 1-3R5M Legion Club	OR'	TONVILLE, MIN	NESOTA
9/22/32 1-307 Replacement 7/13/35 1-1752 High School 11/13/40 1-743J 11/3/46 1-7473 Bakery 4/13/46 1-7473 Schoens Furniture Store 1/25/47 1-387 2/2/48 2-5184 School 7/6/59 1-18475(100\$) South Shore Co-op "Creamery 6/16/50 1-385M American Legion \$\psi 97\$ 7/6/50 2-582 Municipal Hospital 10/9/52 1-385M (15\$) Tahar E.U.B. Church 4/11/60 1-387F Methodist Church			
7/13/35 1-1752 High School 11/13/40 1-743.1 11/3/41 1-0742.1 Bakery 4/13/46 1-747.3 Schoens Furniture Store 1/25/47 1-387 2/2/48 2-5184 School 7/6/49 1-HR25(100\$) South Shore Co-op "Creamery 6/16/50 1-385M American Legion \$97 7/6/50 2-582 Municipal Hospital 7/21/51 2-582(15\$) Nunicipal Hospital 10/9/52 1-385M (15\$) Tahar E.U.B. Church 4/11/60 1-187F Methodist Church	8/15/23	1-5K-15#	
11/13/40 1-743J 11/3/41 1-0742J Bakery 4/13/46 1-7L73 Schoens Furniture Store 1/25/47 1-3R7 2/2/48 2-5184 School 7/6/49 1-HM25(100%) South Shore Co-op "Creamery 6/16/50 1-3R5M American Legion #97 7/6/50 2-582 Municipal Hospital 10/9/52 1-3R5M (15%) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	9/22/32	1-307	Replacement
11/3/41 1-0742J Bakery 4/13/46 1-7L73 Schoens Furniture Store 1/25/47 1-3R7 2/2/48 2-5184 School 7/6/49 1-HM25(100#) South Shore Co-op "Creamery 6/16/50 1-3R5M American Legion #97 7/6/50 2-582 Municipal Hospital 7/21/51 2-582(15#) Municipal Hospital 10/9/52 1-3R5M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	7/13/35	1-1752	High School
4/13/46 1-7173 Schoens Furniture Store 1/25/47 1-387 2/2/48 2-5184 School 7/6/49 1-HM25(1000) South Shore Co-op Creamery 6/16/50 1-385M American Legion #97 7/6/50 2-582 Municipal Hospital 7/21/51 2-582(150) Municipal Hospital 10/9/52 1-385M (150) Tahar E.U.B., Church 4/11/60 1-387F Methodist Church	11/13/40	1-743J	
1/25/47 1-387 2/2/48 2-5184 School 7/6/49 1-HB25(1000) South Shore Co-op "Creamery 6/16/50 1-388M American Legion 097 7/6/50 2-582 Municipal Hospital 7/21/51 2-582(150) Municipal Hospital 10/9/52 1-388% (150) Tahar E.U.B. Church 4/11/60 1-387F Methodist Church	11/3/41	1-0742J	Bakery
2/2/48 2-5184 School 7/6/49 1-HM25(100#) South Shore Co-op Creamery 6/16/50 1-385M American Legion #97 7/6/50 2-582 Municipal Hospital 7/21/51 2-582(15#) Municipal Hospital 10/9/52 1-385M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	4/13/46	1-71.73	Schoens Furniture Store
7/6/49 1-HH25(100#) South Shore Co-op "Creamery 6/16/50 1-3R5M American Legion #97 7/6/50 2-582 Municipal Hospital 7/21/51 2-582(15#) Municipal Hospital 10/9/52 1-3R5M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	1/25/47	1-3R7	
6/16/50 1-3R5M American Legion #97 7/6/50 2-582 Municipal Hospital 7/21/51 2-582(15#) Municipal Hospital 10/9/52 1-3R5M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	2/2/48	2-5184	School
7/6/50 2-582 Municipal Hospital 7/21/51 2-582(15#) Municipal Hospital 10/9/52 1-3R5M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	7/6/49	1-HM25(100#)	South Shore Co-op "Creamery
7/21/51 2-582(15#) Municipal Hospital 10/9/52 1-3R5M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	6/16/50	1-3R5M	American Legion #97
10/9/52 1-3R5M (15#) Tahar E.U.B. Church 4/11/60 1-3R7F Methodist Church	7/6/50	2=582	Municipal Hospital
4/11/60 1-3R7F Methodist Church	7/21/51	2-582(15#)	Municipal Hospital
	10/9/52	1-3R5M (15#)	Tahar E.U.B. Church
11/15/62 1-3R5M Legion Club	4/11/60	1-3R7F	Methodist Church
	11/15/62	1-3R5M	Legion Club

More Free Money





Boiler size (BTU/hr input)	Hot water	High pressure steam	Low pressure steam	Rebate
< or = 300,000	85% A.F.U.E.	81.5%	83%	\$300 to \$500/ MMBTUH, up to \$750/boiler
300,001 - 999,999	83%	81.5%	83%	\$300 to \$500/ MMBTUH, up to \$2,500/boiler
1,000,000 - 9,999,999	83%	81.5%	83%	\$300 to \$500/ MMBTUH up to \$5,000/boiler
10,000,000 or greater	Rebated through the Custom Efficiency program. Must be preapproved			

Description of eligibility	Rebate/incentive/or pricing	
Modular burner controls 5:1 turndown ratio minimum	25% up to \$2,500	
Modular burner controls 10:1 turndown ratio or greater	25% up to \$5,000	
Turbulators	25% up to \$400	
Blowdown heat recovery	25% up to \$5,000	
Steam traps	25% up to \$250 (maximum \$10,000 per site)	
Boiler tune-ups	25% up to \$250	
O2 trim controls	25% up to \$5,000	
Outdoor air reset controls	25% up to \$500	
Stack damper	25% up to \$250	
New boiler systems	See rebate application form (#0550) for details	
Boilers over 10 MMBTUs	Custom Efficiency rebate amount based on energy savings	

More information can be found at http://www.xcelenergy.com

Featured Job


Metro Transit Police Station

Engineer: Howard R. Green - St. Paul, MN Mech Contractor: Dakota P&H - Eagan, MN Equipment: (2) Fulton Pulse PHW500

Installed: Dec 06



What's Wrong? Answers



- Intake pipe should be full 180 gooseneck to prevent wind from blowing in snow, rain
- 2. No rain cap should be used due to high amounts of water vapor which can freeze on the cap.
- 3. Exhaust pipe should be at least 4ft above and 4ft horizontally away from intake air.
- 4. No drain tee is required as unit has built in drain for condensation.





































