



Fulton Pulse Boilers

Recommended Annual Maintenance

1. Replace Spark Plug Igniter.
2. Replace Air Flapper Material. (Gas Flapper Material ever 1½ to 2 years)
3. Have a complete combustion flue gas analysis performed.
4. Clean condensate drain lines and condensate trap assembly.
5. Tighten all wiring terminals.
6. Check exhaust and intake materials for sign of wear and for blockage.



Part Numbers for Recommended Spare Parts

Item	Fulton Pulse Model Numbers					
	300	500	750	1000	1400	2000
Spark Plug Igniter	2-20-90	2-20-90	2-20-90	2-20-90	2-20-90	2-20-90
Fan Proving Switch	2-30-232	2-30-232	2-30-232	2-30-232	2-30-232	2-30-232
Flame Proving Switch	2-30-1334	2-30-1334	2-30-1334	2-30-1334	2-30-1334	2-30-1334
Purge Blower Motor & Fan Assy	2-30-445	2-30-445	2-30-445	2-30-445	2-30-445	2-40-2000
Air Flapper Material (Set)	2-12-551	2-12-551	2-12-551	2-12-551	2-12-553	2-12-554
Gas Flapper Material (Set)	2-12-552	2-12-552	2-12-552	2-12-552	2-12-552	2-12-552

To order these or other parts contact Jesse at the Ryan Company
(952) 915-6475 PH • (952) 915-6480 FX • jesse@ryancompanyinc.com
www.ryancompanyinc.com

Consult your owner's manual for proper installation procedures.